

令和8年度 清輝保育園ほか23施設消防用設備等点検業務委託 数量総括表

園名	自動火災報知設備							屋内消火栓設備			非常警報装置	漏電火災報知器	ガス漏れ報知器	誘導灯	誘導標識	消火器具	避難器具			火災通報装置	非常電源設備	備考
	受信機	発信機	差動式スポット	定温式スポット	体化式	光電式	電鈴	電源	ポンプ	ボックス							すべり台	救助袋	非常階段			
清輝	1	2	27	8		4	2							4		6	1					
三門	1	2	29	17	1	4	3							6		6	1					
津島	1	2	45	17		5	2					2		5		4						
巖井	1	4	52	18	5	7	5							10		8	2					
牟佐	1	2	15	21		4	4							3		8						
緑	1	2	39	22		3	2							5		8				1		
横井	1	2	10	20		9	2							5		8	1					
富原	1	2	19	10		3	3							2		4	1					
吉備津	1	1	21	6		1	2									4						
御津南	1	2	32	9		5	3							6		11						
宇垣	1	2	11	5		3	2									7						
福渡	1	1	13	11		3	3									6						
中山	1	6	61	15	2	17	7							10	6	14	1					
御津金川	1	4	39	12		8	4	1	1	4				10		11				1		
岡南	1	6	47	22		5	8							5		12				1		
建部	1	1	35	5		13	2							4		4				1		
南方・支援セ	1	4	94	20		14		1	1	4	1			17	2	12	1			1	1	
伊島	1	6	18	31		38	6							14		10	1			1		
今	1	4	36	28		8					1		1	21		9			2	1		
鹿田	1	7	46	25		16					1			27		17	1			1	1	
陵南	1	5	34	16		12	5							11		15	1			1		
庄内	1	4	30	12		9	4							10		14	1	1		1		
野谷	1	2	14	17		4	2							4		7	1					
あしもり	1	1	38	10		2	3								7	5						
合計	24	74	805	377	8	197	74	2	2	8	3	2	1	179	15	210	13	1	2	10	2	