

令和8年度 旭東保育園ほか25施設消防用設備等点検業務委託 数量総括表

園名	自動火災報知設備						屋内消火栓設備			非常警報装置	漏電火災報知器	ガス漏れ報知器	誘導灯	誘導標識	消火器具	避難器具			火災通報装置	パッケージ型消火設備	非常電源設備	備考	
	受信機	発信機	差動式スポット	定温式スポット	体化式	光電式	電鈴	電源	ポンプ							ボックス	すべり台	救助袋					非常階段
旭東	1	2	27	26		7	2						5		8	1							
小串	1	1	22	13		1	2					2	1		7								
南輝	1	2	33	13		10	2						5		8	1							
平井	1	3	31	21		3	3						3		8	1							
浜	1	2	22	17		4	4						6		5	2							
平福	1	2	55	9		3	3						1		5								
可知	1	3	30	21		4	4							1	8								
宿毛	1	2	29	15		2	2						1		6								
曾根	1	2	46	15		5	2					1	3		6								
東畦	1	2	28	19		5	2					6	4		7								
興除東	1	2	48	7		3	4								8								
都	1	2	32	17		8	2						5		7				1				
七区	1	2	18	13		2	3						3	8	6								
太伯	2	5	37	19		8	5						10		18	2			1				
灘崎	1	3	52	21		30	3	1	1	3	1		12		10				1			1	
千種	1	2	28	5		5	2						5		8			1					
甲浦	1	5	27	26		6	5						9		6	1		1	1				
興除	1	4	54	28		8	4						9		11	1			1				
錦	1	3	33	15		7	3						5		6								
旭竜	1	5	40	27		8	5						15		9	1			1				
宇野	1	4	31	30		15	4						23		9	1			1		1		
妹尾	1	7	33	16		9	7						10		12	1							
政田開成	1	2	27	13		10	2						6		5				1				
浦安芳泉	1	4	47	28		12	4						6		10	1			1				
西大寺	1	1	71	25		13	4						14		16	1	2		1			1	
幡多	1	4	43	8		16	4						17		6	1	1		1				
合計	27	76	944	467	0	204	87	1	1	3	1	3	6	178	9	215	15	3	2	11	1	2	